



HISTORIC PRESERVATION

Deconstruction

BUILD DATE CONFIRMATION



PART 1: PRIMARY SOURCES

Appears on a Sanborn Fire Insurance Map Yes No

Year, Volume, Sheet **1931 (volume 3, sheet 283)**

If yes, is there evidence that the same structure is present today? Yes No

Explain

Same location and footprint

Listed in a San Antonio City Directory Yes No

Earliest Year **1934 (p 1186)**



PART 2: ARCHITECTURAL ASSESSMENT

Is there evidence of any of the following historic characteristics: Yes No
Circle which are present

Style: Vernacular Folk Victorian Queen Anne Craftsman Revival Other: Tudor revival

Form: Wing and Gable Linear Steeply Pitched Roof Hipped Roof Other:

Materials: Stone Caliche Adobe Wood Siding Wood Windows Other: brick



PART 3: OTHER RESOURCES

Does the property appear in any of the following supplementary resources?

Only complete if all responses in Part 1 are No and the response to Part 2 is Yes.

Newspapers: _____

Property Records: _____

Other (previous surveys, other archival resources including maps, photographs, or books):

Present on aerials in 1939 per HistoricAerials.com

1122 Delaware

Historic District, Landmark, or
Neighborhood Conservation District

NA

City Council District /
Neighborhood Association

CD2 / Denver Heights NA

Build Date

Deconstruction Required?

c 1931

YES

NO