

345 BRAHAN BLVD. – EXISTING WINDOW & DOOR PHOTO SCHEDULE


OHP Package – Final

Fenderson Residence Remodel • San Antonio, Texas • August 27, 2026

Source schedule	Brahan_OHP_Existing_Openings_Schedule_Reconciled_RevC.csv
Total openings	50 (42 windows, 8 doors)
Image resolution status	89 / 89 referenced images resolved from uploaded ZIP files
Included plan maps	1F Existing Fenestration Map, 2F Existing Fenestration Map


First Floor Existing Fenestration Reference Map

Reference plan sheet showing existing opening locations. Detailed photo schedule follows.



Second Floor Existing Fenestration Reference Map

Reference plan sheet showing existing opening locations. Detailed photo schedule follows.



W-01 — Window

Floor 1 • Laundry

Orientation:	North	Historic/Material Note:	Original
Existing Size:	36 x 42	Interior Photo Ref:	IMG_3858
Existing RO:	—	Exterior Photo Ref:	IMG_3580
Known Scope:	Retain / repair		



Interior View — IMG_3858



Exterior View — IMG_3580

W-02 — Window

Floor 1 • Laundry

Orientation:	West	Historic/Material Note:	Original
Existing Size:	36 x 42	Interior Photo Ref:	IMG_3859
Existing RO:	—	Exterior Photo Ref:	IMG_3581
Known Scope:	Retain / repair		



Interior View — IMG_3859



Exterior View — IMG_3581


W-03 — Window

Floor 1 • Mudroom

Orientation:	North - eastmost	Historic/Material Note:	Not original - aluminum jalousie
Existing Size:	16 1/4 x 62	Interior Photo Ref:	IMG_3857
Existing RO:	—	Exterior Photo Ref:	IMG_3579
Known Scope:	Remove with north-wall redesign		



Interior View — IMG_3857



Exterior View — IMG_3579


W-04 — Window

Floor 1 • Mudroom

Orientation:	North - west jalousie	Historic/Material Note:	Not original - aluminum jalousie
Existing Size:	22 3/4 x 62	Interior Photo Ref:	IMG_3857
Existing RO:	—	Exterior Photo Ref:	IMG_3579
Known Scope:	Remove with north-wall redesign		



Interior View — IMG_3857



Exterior View — IMG_3579


W-05 — Window

Floor 1 • Mudroom

Orientation:	North - westmost	Historic/Material Note:	Not original - aluminum
Existing Size:	47 x 62	Interior Photo Ref:	IMG_3857
Existing RO:	—	Exterior Photo Ref:	IMG_3579
Known Scope:	Remove with north-wall redesign		



Interior View — IMG_3857



Exterior View — IMG_3579

W-06 — Window

Floor 1 • Kitchen bay

Orientation:	West side	Historic/Material Note:	Unconfirmed - Newer Style
Existing Size:	20 x 43	Interior Photo Ref:	IMG_3483
Existing RO:	—	Exterior Photo Ref:	IMG_3576
Known Scope:	Retain / repair		



Interior View — IMG_3483



Exterior View — IMG_3576

W-07 — Window

Floor 1 • Kitchen bay

Orientation:	North / center	Historic/Material Note:	Unconfirmed - Newer Style
Existing Size:	44 x 43	Interior Photo Ref:	IMG_3482
Existing RO:	—	Exterior Photo Ref:	IMG_3578
Known Scope:	Retain / repair		



Interior View — IMG_3482



Exterior View — IMG_3578

W-08 — Window

Floor 1 • Kitchen bay

Orientation:	East side	Historic/Material Note:	Unconfirmed - Newer Style
Existing Size:	20 x 43	Interior Photo Ref:	IMG_3481
Existing RO:	—	Exterior Photo Ref:	IMG_3577
Known Scope:	Retain / repair		



Interior View — IMG_3481



Exterior View — IMG_3577

W-09 — Window

Floor 1 • Pantry

Orientation:	Exterior wall	Historic/Material Note:	Unconfirmed
Existing Size:	30 x 36	Interior Photo Ref:	IMG_3856
Existing RO:	—	Exterior Photo Ref:	IMG_3866
Known Scope:	Retain / repair		



Interior View — IMG_3856




Exterior View — IMG_3866

W-10 — Window

Floor 1 • Dining

Orientation:	North - East assembly	Historic/Material Note:	Not original - aluminum
Existing Size:	121 x 62 1/2	Interior Photo Ref:	IMG_3485
Existing RO:	—	Exterior Photo Ref:	IMG_3493
Known Scope:	Remove with north-wall redesign		




W-11 — Window

Floor 1 • Dining

Orientation:	North - West assembly	Historic/Material Note:	Not original - aluminum
Existing Size:	121 x 62 1/2	Interior Photo Ref:	IMG_3484
Existing RO:	—	Exterior Photo Ref:	IMG_3493
Known Scope:	Remove with north-wall redesign		



Interior View — IMG_3484



Exterior View — IMG_3493

W-12 — Window

Floor 1 • Dining

Orientation:	East	Historic/Material Note:	Not original - aluminum
Existing Size:	32 x 60	Interior Photo Ref:	IMG_3864
Existing RO:	—	Exterior Photo Ref:	IMG_3863
Known Scope:	Remove with dining redesign		



Interior View — IMG_3864



Exterior View — IMG_3863

W-13 — Window

Floor 1 • Den

Orientation:	West - north window	Historic/Material Note:	Original
Existing Size:	36 x 55	Interior Photo Ref:	IMG_3855
Existing RO:	—	Exterior Photo Ref:	IMG_3584
Known Scope:	Remove for future 4-panel door assembly		



Interior View — IMG_3855



Exterior View — IMG_3584

W-14 — Window

Floor 1 • Den

Orientation:	West - south window	Historic/Material Note:	Original
Existing Size:	36 x 55	Interior Photo Ref:	IMG_3854
Existing RO:	—	Exterior Photo Ref:	IMG_3585
Known Scope:	Remove for future 4-panel door assembly		



Interior View — IMG_3854





Exterior View — IMG_3585

W-15 — Window

Floor 1 • Den bay



Orientation:	Side A	Historic/Material Note:	Original
Existing Size:	30 x 62	Interior Photo Ref:	IMG_3466
Existing RO:	—	Exterior Photo Ref:	IMG_3447
Known Scope:	Retain / repair		



W-16 — Window

Floor 1 • Den bay



Orientation:	Center	Historic/Material Note:	Original
Existing Size:	36 x 62	Interior Photo Ref:	IMG_3466
Existing RO:	—	Exterior Photo Ref:	IMG_3448
Known Scope:	Retain / repair		



W-17 — Window

Floor 1 • Den bay

Orientation:	Side B	Historic/Material Note:	Original
Existing Size:	30 x 62	Interior Photo Ref:	IMG_3466
Existing RO:	—	Exterior Photo Ref:	IMG_3449
Known Scope:	Retain / repair		



W-18 — Window

Floor 1 • Living room

Orientation:	South - west	Historic/Material Note:	Original
Existing Size:	42 x 78	Interior Photo Ref:	IMG_3451
Existing RO:	—	Exterior Photo Ref:	IMG_3849
Known Scope:	Retain / repair		



Interior View — IMG_3451



Exterior View — IMG_3849

W-19 — Window

Floor 1 • Living room

Orientation:	South - east	Historic/Material Note:	Original
Existing Size:	42 x 78	Interior Photo Ref:	IMG_3450
Existing RO:	—	Exterior Photo Ref:	IMG_3436
Known Scope:	Retain / repair		



Interior View — IMG_3450



Exterior View — IMG_3436

W-20 — Window

Floor 1 • East wing bath

Orientation:	South	Historic/Material Note:	Original
Existing Size:	28 x 45	Interior Photo Ref:	IMG_3435
Existing RO:	—	Exterior Photo Ref:	IMG_3442
Known Scope:	Retain / repair		



Interior View — IMG_3435



Exterior View — IMG_3442

W-21 — Window

Floor 1 • East wing

Orientation:	North - west of patio doors	Historic/Material Note:	Exterior presently boxed/covered
Existing Size:	36 x 44 1/4	Interior Photo Ref:	IMG_3433
Existing RO:	37 1/8 x 46	Exterior Photo Ref:	IMG_3850
Known Scope:	Retain / repair - remove cover		



Interior View — IMG_3433



Exterior View — IMG_3850

W-22 — Window

Floor 1 • East wing NE corner

Orientation:	North face	Historic/Material Note:	Original
Existing Size:	53 5/8 x 81 1/4 x 5 jamb	Interior Photo Ref:	IMG_3427
Existing RO:	54 1/2 x 83 1/2	Exterior Photo Ref:	IMG_3446
Known Scope:	Replace in existing RO		



Interior View — IMG_3427



Exterior View — IMG_3446

W-23 — Window

Floor 1 • East wing NE corner

Orientation:	East face	Historic/Material Note:	Original
Existing Size:	53 5/8 x 81 1/4 x 5 jamb	Interior Photo Ref:	IMG_3428
Existing RO:	54 1/2 x 83 1/2	Exterior Photo Ref:	IMG_3445
Known Scope:	Replace in existing RO		



Interior View — IMG_3428




Exterior View — IMG_3445

W-24 — Window

Floor 1 • East wing SE corner



Orientation:	Narrower assembly	Historic/Material Note:	Not original
Existing Size:	74 1/2 x 51 x 4 1/2 jamb	Interior Photo Ref:	IMG_3982
Existing RO:	79 x 52 3/4	Exterior Photo Ref:	IMG_3444
Known Scope:	Replace in existing RO		



W-25 — Window

Floor 1 • East wing SE corner

Orientation:	Wider assembly	Historic/Material Note:	Not original
Existing Size:	102 x 51 x 4 1/2 jamb	Interior Photo Ref:	IMG_3983
Existing RO:	105 3/4 x 52 3/4	Exterior Photo Ref:	IMG_3443
Known Scope:	Replace in existing RO		



W-26 — Window

Floor 2 • West room

Orientation:	North - west	Historic/Material Note:	Original
Existing Size:	34 x 54	Interior Photo Ref:	IMG_3527
Existing RO:	—	Exterior Photo Ref:	IMG_3500
Known Scope:	Retain / repair		



Interior View — IMG_3527



Exterior View — IMG_3500

W-27 — Window

Floor 2 • West room

Orientation:	North - east	Historic/Material Note:	Original
Existing Size:	34 x 54	Interior Photo Ref:	IMG_3528
Existing RO:	—	Exterior Photo Ref:	IMG_3499
Known Scope:	Retain / repair		



Interior View — IMG_3528



Exterior View — IMG_3499

W-28 — Window

Floor 2 • West room

Orientation:	West	Historic/Material Note:	Original
Existing Size:	34 x 54	Interior Photo Ref:	IMG_3526
Existing RO:	—	Exterior Photo Ref:	IMG_3591
Known Scope:	Retain / repair		



Interior View — IMG_3526



Exterior View — IMG_3591

W-29 — Window

Floor 2 • West room

Orientation:	South - west	Historic/Material Note:	Original
Existing Size:	34 x 54	Interior Photo Ref:	IMG_3521
Existing RO:	—	Exterior Photo Ref:	IMG_3522
Known Scope:	Retain / repair		



Interior View — IMG_3521



Exterior View — IMG_3522

W-30 — Window

Floor 2 • West room

Orientation:	South - east	Historic/Material Note:	Original
Existing Size:	34 x 54	Interior Photo Ref:	IMG_3520
Existing RO:	—	Exterior Photo Ref:	IMG_3523
Known Scope:	Retain / repair		



Interior View — IMG_3520



Exterior View — IMG_3523

W-31 — Window

Floor 2 • Wardrobe / bath

Orientation:	North - type A1	Historic/Material Note:	Original
Existing Size:	38 x 46	Interior Photo Ref:	IMG_3541
Existing RO:	—	Exterior Photo Ref:	IMG_3495
Known Scope:	Retain / repair		



Interior View — IMG_3541



Exterior View — IMG_3495

W-32 — Window

Floor 2 • Wardrobe / bath

Orientation:	North - type B1	Historic/Material Note:	Original
Existing Size:	18 x 42	Interior Photo Ref:	IMG_3531
Existing RO:	—	Exterior Photo Ref:	IMG_3496
Known Scope:	Retain / repair		



Interior View — IMG_3531



Exterior View — IMG_3496

W-33 — Window

Floor 2 • Wardrobe / bath

Orientation:	North - type B2	Historic/Material Note:	Original
Existing Size:	18 x 42	Interior Photo Ref:	IMG_3530
Existing RO:	—	Exterior Photo Ref:	IMG_3497
Known Scope:	Retain / repair		



Interior View — IMG_3530



Exterior View — IMG_3497

W-34 — Window

Floor 2 • Wardrobe / bath

Orientation:	North - type A2	Historic/Material Note:	Original
Existing Size:	38 x 46	Interior Photo Ref:	IMG_3529
Existing RO:	—	Exterior Photo Ref:	IMG_3498
Known Scope:	Retain / repair		



Interior View — IMG_3529



Exterior View — IMG_3498

W-35 — Window

Floor 2 • East bedroom

Orientation:	North - west	Historic/Material Note:	Original
Existing Size:	34 x 54	Interior Photo Ref:	IMG_3539
Existing RO:	—	Exterior Photo Ref:	IMG_3494
Known Scope:	Retain / repair		



Interior View — IMG_3539



Exterior View — IMG_3494

W-36 — Window

Floor 2 • East bedroom

Orientation:	North - east	Historic/Material Note:	Original
Existing Size:	34 x 54	Interior Photo Ref:	IMG_3537
Existing RO:	—	Exterior Photo Ref:	IMG_3494
Known Scope:	Retain / repair		



Interior View — IMG_3537



Exterior View — IMG_3494

W-37 — Window

Floor 2 • Hall / east-bedroom group

Orientation:	South - westmost	Historic/Material Note:	Original
Existing Size:	34 x 47	Interior Photo Ref:	IMG_3532
Existing RO:	—	Exterior Photo Ref:	IMG_3439
Known Scope:	Retain / repair		



Interior View — IMG_3532



Exterior View — IMG_3439

W-38 — Window

Floor 2 • Hall / east-bedroom group

Orientation:	South - center	Historic/Material Note:	Original
Existing Size:	34 x 47	Interior Photo Ref:	IMG_3533
Existing RO:	—	Exterior Photo Ref:	IMG_3440
Known Scope:	Retain / repair		



Interior View — IMG_3533



Exterior View — IMG_3440

W-39 — Window

Floor 2 • Hall / east-bedroom group

Orientation:	South - eastmost	Historic/Material Note:	Original
Existing Size:	34 x 47	Interior Photo Ref:	IMG_3534
Existing RO:	—	Exterior Photo Ref:	IMG_3441
Known Scope:	Retain / repair		



Interior View — IMG_3534



Exterior View — IMG_3441

W-40 — Window

Floor 2 • Stairwell

Orientation:	South	Historic/Material Note:	Original
Existing Size:	36 x 77	Interior Photo Ref:	IMG_3515
Existing RO:	—	Exterior Photo Ref:	IMG_3438
Known Scope:	Retain / repair		



Interior View — IMG_3515



Exterior View — IMG_3438

W-41 — Window

Floor 2 • East bedroom

Orientation:	East - northernmost	Historic/Material Note:	Original
Existing Size:	36 x 51	Interior Photo Ref:	IMG_3536
Existing RO:	36 1/2 x 51 1/4	Exterior Photo Ref:	IMG_3802
Known Scope:	Damaged - Replace in existing RO with wood window		



Interior View — IMG_3536



Exterior View — IMG_3802

W-42 — Window

Floor 2 • East bedroom

Orientation:	East - southern	Historic/Material Note:	Original
Existing Size:	36 x 51	Interior Photo Ref:	IMG_3535
Existing RO:	—	Exterior Photo Ref:	IMG_3802
Known Scope:	Retain / repair		



Interior View — IMG_3535



Exterior View — IMG_3802

D-01 — Door

Floor 1 • Front entry

Orientation:	South / front	Historic/Material Note:	Original
Existing Size:	44 1/4 x 83	Interior Photo Ref:	IMG_3909
Existing RO:	—	Exterior Photo Ref:	IMG_3437
Known Scope:	Retain / repair		



Interior View — IMG_3909



Exterior View — IMG_3437


D-02 — Door

Floor 1 • Mudroom

Orientation:	North	Historic/Material Note:	Not original
Existing Size:	36 x 79 1/2	Interior Photo Ref:	IMG_3857
Existing RO:	—	Exterior Photo Ref:	IMG_3579
Known Scope:	Damaged - Remove with north-wall redesign		



Interior View — IMG_3857



Exterior View — IMG_3579

D-03 — Door

Floor 1 • Mudroom

Orientation:	South	Historic/Material Note:	Unconfirmed
Existing Size:	35 3/4 x 85 1/2	Interior Photo Ref:	IMG_3911
Existing RO:	—	Exterior Photo Ref:	IMG_3583
Known Scope:	Damaged - Replace with new arch door		



Interior View — IMG_3911



Exterior View — IMG_3583

D-04 — Door

Floor 1 • Dining

Orientation:	East	Historic/Material Note:	Not original
Existing Size:	36 x 80	Interior Photo Ref:	IMG_3486
Existing RO:	—	Exterior Photo Ref:	IMG_3490
Known Scope:	Remove for future 4-panel door assembly redesign		



Interior View — IMG_3486



Exterior View — IMG_3490

D-05 — Door

Floor 1 • Living room

Orientation:	NE / patio N	Historic/Material Note:	Original
Existing Size:	50 1/2 x 81 1/2	Interior Photo Ref:	IMG_3907
Existing RO:	51 3/8 x 82 1/2	Exterior Photo Ref:	IMG_3487
Known Scope:	Retain / repair		



Interior View — IMG_3907



Exterior View — IMG_3487

D-06 — Door

Floor 1 • Living room

Orientation:	NE / patio E	Historic/Material Note:	Original
Existing Size:	50 1/2 x 81 1/2	Interior Photo Ref:	IMG_3908
Existing RO:	51 3/8 x 82 1/2	Exterior Photo Ref:	IMG_3489
Known Scope:	Retain / repair		



Interior View — IMG_3908



Exterior View — IMG_3489

D-07 — Door

Floor 1 • East wing

Orientation:	North patio / French doors	Historic/Material Note:	Original
Existing Size:	50 1/2 x 81 1/2	Interior Photo Ref:	IMG_3432
Existing RO:	51 1/2 x 82 1/4	Exterior Photo Ref:	IMG_3488
Known Scope:	Retain / repair		



Interior View — IMG_3432



Exterior View — IMG_3488

D-08 — Door

Floor 2 • West room

Orientation:	Balcony	Historic/Material Note:	Original
Existing Size:	50 1/2 x 81 1/2	Interior Photo Ref:	IMG_3525
Existing RO:	—	Exterior Photo Ref:	IMG_3524
Known Scope:	Retain / repair		



Interior View — IMG_3525



Exterior View — IMG_3524