



HISTORIC PRESERVATION

Deconstruction

BUILD DATE CONFIRMATION



PART 1: PRIMARY SOURCES

Appears on a Sanborn Fire Insurance Map Yes No

Year, Volume, Sheet **1912 (As 827 Aransas Av; vol 3, sheet 289)**

If yes, is there evidence that the same structure is present today? Yes No
Explain

Same footprint and location

Listed in a San Antonio City Directory Yes No

Earliest Year **1903 (as 827 Aransas, p 260 of HeritageQuest volume)**



PART 2: ARCHITECTURAL ASSESSMENT

Is there evidence of any of the following historic characteristics: Yes No
Circle which are present

Style: Vernacular Folk Victorian Queen Anne Craftsman Revival Other:

Form: Wing and Gable Linear Steeply Pitched Roof Hipped Roof Other:

Materials: Stone Caliche Adobe Wood Siding Wood Windows Other:



PART 3: OTHER RESOURCES

Does the property appear in any of the following supplementary resources?

Only complete if all responses in Part 1 are No and the response to Part 2 is Yes.

Newspapers:

Property Records:

Other (previous surveys, other archival resources including maps, photographs, or books):

Present on aerials in 1939 per HistoricAerials.com

743 Aransas Ave

Historic District, Landmark, or
Neighborhood Conservation District

NA

City Council District /
Neighborhood Association

CD2 / Denver Heights

Build Date

Deconstruction Required?

c 1903

YES

NO