



HISTORIC PRESERVATION

Deconstruction

BUILD DATE CONFIRMATION



PART 1: PRIMARY SOURCES

Appears on a Sanborn Fire Insurance Map Yes No

Year, Volume, Sheet 1931 (As 1418-1418 1/2 W Magnolia, vol 1, sheet 47)

If yes, is there evidence that the same structure is present today? Yes No
Explain

Same footprint and location for primary; current accessory built by 2008

Listed in a San Antonio City Directory Yes No

Earliest Year 1926 (as 1418-1418 1/2 W Magnolia; p 1425)



PART 2: ARCHITECTURAL ASSESSMENT

Is there evidence of any of the following historic characteristics: Yes No
Circle which are present

Style: Vernacular Folk Victorian Queen Anne Craftsman Revival Other:

Form: Wing and Gable Linear Steeply Pitched Roof Hipped Roof Other:

Materials: Stone Caliche Adobe Wood Siding Wood Windows Other:



PART 3: OTHER RESOURCES

Does the property appear in any of the following supplementary resources?

Only complete if all responses in Part 1 are No and the response to Part 2 is Yes.

Newspapers:

Property Records:

Other (previous surveys, other archival resources including maps, photographs, or books):

Primary on aerials in 1939 per HistoricAerials.com; accessory does not require decon.

1416 W Magnolia St

Historic District, Landmark, or
Neighborhood Conservation District

NA

City Council District /
Neighborhood Association

CD1 / Jefferson NA

Build Date

Deconstruction Required?

c 1926

YES

NO