

21

22



2nd Floor
Bedroom North

Interior

22

21




23



2nd Floor
Hallway

23 Interior




24



2nd Floor
Guest Bath

24 Interior



25

26



2nd Floor
Primary Bedroom Northwest


Interior

26

25




27



2nd Floor
Primary Bath Northwest

27 Interior



28



2nd Floor
Primary Closet West

28 Interior




29



2nd Floor
Primary Staircase

29 Interior



30

31



2nd Story
Primary Closet East

Interior

31

30



32

33



2nd Story
Primary Bedroom East

Interior

33

32




34



2nd Floor
Staircase

34 Interior






2nd Floor
Guest Bedroom 1 South

Interior

36

35




37



2nd Floor
Guest Bedroom 1 East

37 Interior



2nd Floor
Guest Bedroom 1 East

38

39



2nd Floor
Guest Bedroom 2 South


Interior

39

38



40



2nd Floor
Guest Bedroom 2 East

40 Interior



2nd Floor
Guest Bedroom 2 East



Overall window condition



overall window condition



overall window condition