

Deconstruction

BUILD DATECONFIRMATION

Address				
215 Dumoulin Ave	;			
Historic District, Landmark, or Neighborhood Conservation District				
NA				
City Council District / Neighborhood Association				
CD2 / Denver Heights NA				
Build Date	Deco	nstructi	on Requir	ed?
c 1922		YES	NO C)

I CONFIF	RMATION			
PART 1: PRI	IMARY SOURCES			
Appears on a Sanborn Fire Insurance Map Oyes No				
Year, Volume, Sheet	1931 (vol 3 sheet 290)			
If yes, is there evid Explain	lence that the same structure is present today?			
same footprint and loca	ition			
Listed in a San Ant	tonio City Directory			
Earliest Year	1922 (p 87)			
PART 2: AR	CHITECTURAL ASSESSMENT			
Is there evidence o Circle which are pres	of any of the following historic characteristics: Yes No ent			
Style: Vernacular	Folk Victorian Queen Anne Craftsman Revival Other:			
Form: Wing and Ga	able Linear Steeply Pitched Roof Hipped Roof Other:			
Materials: Stone	Caliche Adobe Wood Siding Wood Windows Other:			
PART 3: OT	HER RESOURCES			
	appear in any of the following supplementary resources? esponses in Part 1 are No and the response to Part 2 is Yes.			
Newspapers:				
Property Records:				
"	erials (via HistoricAerials.com)			