

Statement of Loss of Significance – 415 Furr Dr

The detached garage located on the property of 415 Furr dr has a roof that is structurally compromised. The weight of the roof is held up with two jacks at the front of the structure. The homeowner also informed me that the back wall facing the alley has been struck and is bowed in. She also stated that when she got a quote to have it repaired, they realized that the 2x4's on the interior of the frame are rotten and not attached to any footing or foundation.