

Property

Address	509 Nolan
District/Overlay	Dignowity Hill

Site Visit

Oile visit	
Date	05/10/2024
Time	02:01 PM (-5 GMT)
Context	citizen report, drive-by
Present Staff	Claudia Espinosa
Present Individuals	None
Contractor/Realtor Companies	JEVE CONSTRUCTION LLC
Types of Work Observed	Exterior Maintenance and Alterations
Amount of Work Completed	Initiated
Description of work	Window removal on East and west facades.
Description of interaction	Staff received a report of window removal on the east side of the property. Staff observed window removal on the rear of the east and west facades. No one was on site to discuss the reported violations or COA process. Staff left a SWO on the mailbox.

Action Taken

Violation Type	No Certificate of Appropriateness (Code 35-451a)
OHP Action	Posted additional "Stop Work Notice"
Will post-work application fee apply?	To be determined

Documentation




Photographs





























































05/10/2024 02:05 PM